



CATALOG ERROR CORRECTION NOTICE

Exhaust & Intake Catalog, Part Number LT1004

Please be aware that there is an error in our newest LT1004 exhaust catalog. On page 14 of the LT1004 catalog published 9/07, we show the measurement method as a centerline measurement. This is not correct. The correct measurement method is shown on page 17 of this current catalog. We hope this hasn't caused too much confusion. We will continue to sell elbows based on this measurement method.



If you have questions regarding this correction, contact a **PowerProducts Account Manager**

www.e-pdc.com

